NPS-69PS-78-005

# NAVAL POSTGRADUATE SCHOOL

Monterey, California



MORPHOLOGICAL EVIDENCE FOR A PITTING MECHANISM IN DILUTE ALUMINUM ALLOYS

bу

J. Perkins, J. R. Cummings and K. J. Graham

June 1978

FEDDOCS D 208.14/2:NPS-69PS-78-005 the Office of Naval Research tract No. NO0014-78-WR-80105

Approved for public release; distribution unlimited.

Reproduction in whole or in part is permitted for any purpose of the United States Government.

# NAVAL POSTGRADUATE SCHOOL Monterey, California

Rear Admiral T. R. Dedman Superintendent

Jack R. Borsting Provost

The work reported herein was supported by the Office of Naval Research, Naval Ship Systems Command, Metallurgy Program Office, Code 471, Arlington, VA, 22217, through Contract No. NO0014-78-WR-80105, NR-036-120.

Reproduction of all or part of this report is authorized.

This report was prepared by:

#### UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
NPS-69PS-78-005		
4. TITLE (and Subtitle)		S. TYPE OF REPORT & PERIOD COVERED
MORPHOLOGICAL EVIDENCE FOR A PITTING MECHANISM IN DILUTE ALUMINUM ALLOYS		Interim, 3/78 <b>to</b> 6/78
		6. PERFORMING ORG. REPORT NUMBER Technical Report No. 9
7. AUTHOR(s)		B. CONTRACT OR GRANT NUMBER(a)
J. PERKINS, J. R. CUMMINGS AND K. J. GRAHAM		N00014-78-WR-80105, NR-036-120
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
Materials Science and Chemistry Group, Dept. of Mechanical Engineering, Naval Postgraduate School, Monterey, CA 93940		AREA & WORK UNIT NUMBERS
		Program Element: 61153N Project: RRO22-08-01
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE
Office of Naval Research, Metallurg	y Program	June 1978
Office, Code 471, Arlington, VA 22217		13. NUMBER OF PAGES
14. MONITORING AGENCY NAME & ADDRESS(If different	from Controlling Office)	1S. SECURITY CLASS. (of this report)
		UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE

16. DISTRIBUTION STATEMENT (of this Report)

Approved for public release; distribution unlimited.

Reproduction in whole or in part is permitted for any purpose of the United States Government.

17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)

18. SUPPLEMENTARY NOTES

19. KEY WORDS (Continue on reverse side if necessary and identify by block number)

pitting, aluminum alloys, corrosion products, scanning electron microscopy.

20. ABSTRACT (Continue on reverse side if necessary and identify by block number)

In the course of an investigation of the seawater corrosion behavior of several dilute aluminum alloys, direct microscopic evidence of pitting phenomena was obtained. Observations, obtained by scanning electron microscopy after gal-vanic corrosion exposures, illustrate a pitting mechanism involving the extrusion of columns of corrosion product from pits by the action of hydrogen gas generated inside the pits. The macroscopic dissolution patterns of the various alloys and their respective microscopic dissolution morphologies

# MORPHOLOGICAL EVIDENCE FOR A PITTING MECHANISM IN DILUTE ALUMINUM ALLOYS

J. Perkins, J. R. Cummings, and K. J. Graham Materials Science and Chemistry Group, Code 61Ps Naval Postgraduate School, Monterey, CA 93940

In the course of a recent investigation (1) of the saltwater corrosion behavior of several dilute aluminum alloys, some dramatic direct microscopic evidence of pitting phenomena was obtained. Observations, obtained by scanning electron microscopy after galvanic corrosion exposures, illustrate a pitting mechanism involving the extrusion of columns of corrosion product from pits by the action of hydrogen gas generated inside the pits. Because this behavior does not relate directly to the goals of the original study of these alloys (1), it is being reported separately in this note.

The alloys investigated were several dilute aluminum alloys designed especially for application as sacrificial anodes in marine cathodic protection systems. The nominal compositions of the alloys discussed in this note are given in Table I. These alloys were exposed in natural galvanic couples (area ratio 1:27) with steel in aerated synthetic seawater; the experimental details have been presented in an earlier report (1). Under these conditions, the aluminum alloys (which were monitored for galvanic current and potential) operated with a steady-state anodic current density of about 0.8 mA/cm<sup>2</sup> and the anodic polarization of the alloys was to about -1.0V (vs.SCE); (the corrosion potentials of the three alloys G, R, and K were measured (1) as -1.35, -1.15, and -1.2V, all vs.SCE, respectively).

## Macroscopic Dissolution Behavior

Each of the dilute aluminum alloys has its own unique pattern of dissolution on the macroscopic scale. Alloy G tends to initiate large dissolution cavities along the machined edges and corners of samples (Figure la), Alloy R forms vertically aligned elongated dissolution cavities on the broad faces (Figure lb), and Alloy K tends to exhibit profuse pitting (lc). These behaviors have been discussed in an earlier report (l) and will not be considered in detail here. The active regions of the anodes are confined to the

dissolution regions; the rest of the surface is covered with a thin compact film. All of the alloys tend to rapidly form (within a few hours) a certain distribution of initial disolution sites, which then slowly expand laterally, as opposed to initiation of more sites.

The dissolution surfaces of Alloys G and R accumulate little if any corrosion product in the early stages of attack (first 50 hours) while Alloy K shows distinctly more accumulation than the other alloys, with about as much product after 1 hour as the others show in 50 hours (1). Only after the dissolution surfaces become somewhat filmed-over with corrosion product do the fine (micron scale) pits discussed in this paper appear; i.e., these fine pits are not an initial phenomena, and are distinguished from the larger initial dissolution cavities. The samples, exposed in galvanic couples, initially experience a relatively high current density (about 4 to 8 mA/cm<sup>2</sup>) which then falls off to a stable level of about 0.8 mA/cm<sup>2</sup> (1); this decrease corresponds mainly to the accumulation of calcareous deposits on the surfaces of the companion cathodes (steel); this reduces the galvanic current, and when the current falls, and the aluminum anodes are less active, they tend to develop corrosion product films over their dissolution regions (1). When this occurs, the conditions are apparently established for true pitting phenomena, i.e., occluded cells are established, and attack accelerates perpendicular to the surface, forming deep pin-hole cavities.

## Microscopic Dissolution Behavior

When the dissolution surfaces of these alloys are examined at high magnification in the scanning electron microscope, each alloy is seen to have its own characteristic dissolution morphology. In each case, the attack is distinctly crystallographic in nature, but the specific form differs for each alloy, as illustrated in Figure 2. Alloy G exhibits a unique step pattern, with very little corrosion product accumulation (Figure 2a). Alloy R developes a distinctly different dissolution morphology, consisting of an array of sharp crystallographic peaks (Figure 2b) and in this case also there is little corrosion product on the reacting areas of the surface. Alloy K shows a much less distinct etching pattern than the other alloys, and there is a tendency to accumulate more corrosion product, so that the underlying dissolution morphology is only seen when the corrosion product is knocked off the surface; a tendency to intergranular penetration is also seen for Alloy K. Of course,

because the alloys are exhibiting crystallographic etching, the exact appearance of the dissolution pattern varies with grain orientation (1).

#### Microscopic Observations of a Pitting Mechanism

After about 50 hours galvanic exposure, Alloys G and R begin to develop a discontinuous film over their dissolution surfaces. When this occurs, evidence of a true pitting phenomenon begins to be seen. Mushroom-like mounds of corrosion product begin to push their way up at certain sites in the film (Figure 3a). These emerging forms characteristically have a smooth hemispherical cap, and by their form appear to be discontinuously extruded from within the underlying pits (Figure 3b). These eruptions are nearly always located within the mud-cracked film over the dissolution regions; only occasionally are such forms seen to emerge on the unattacked areas of the surface (Figures 4a, 4b). These forms are assumed to consist of a hydrated aluminum oxide corrosion product which has been emitted from the pit mouths by the action of hydrogen gas pressure built up within the occluded cells (pits).

Alloy K shows a somewhat different morphological manifestation of fine-scale pitting phenomenon, consisting of arrays of perfectly hemispherical hollow domes located on the unattacked surface areas of the anode (Figure 3c). These appear much earlier in the exposure history of the anode than the extruded forms on Alloys G and R. These forms again appear to be the result of hydrogen gas evolution within underlying pits. In this case, the pressure inflates the domes by deformation of the general film material. These domes are known to be thin hollow shells because they often are observed broken open (Figure 5), probably due to handling of the specimens. Even when the surface is studied at high magnification, these domes cannot be clearly associated with any physical feature in the general film structure, such as cracks; note in Figure 3c that the general film reflects the underlying grinding marks on the specimen. When these hemispherical pods crack open, an interior filament of very white corrosion product can be seen (Figure 5).

### Discussion

Aluminum is well-known to pit in chloride-containing aqueous solutions, including seawater (2-6). In this study, the initiation of dissolution is accomplished in all three alloys by the formation of local regions in the surface film. These dissolution regions tend to spread laterally over the surface

more rapidly than they penetrate, the anodic and cathodic reactions are not separated, and occluded cells are not formed; thus, this behavior is not based on a classical pitting mechanism. However, later in the history of the samples, when the dissolution regions become somewhat filmed over with corrosion product, true pitting phenomena is exhibited, with separated anodic and cathodic reaction sites, occluded cells, and accelerated penetration perpendicular to the surface.

In a solution such as seawater, the natural anodic and cathodic halfcell reactions on aluminum may be considered to be

(1) A1 
$$\rightarrow$$
 A1<sup>+++</sup> + 3e<sup>-</sup>

and (2) 
$$0_2 + 2H_20 + 4e^- \rightarrow 40H^-$$

respectively. Without considering the exact mechanism by which the true pits initiate, which is historically a controversial matter (7-11), we may assume that when the pits initiate these half-cell reactions become physically separated, with the aluminum dissolution reaction occurring within the pit site, and the oxygen reduction reaction occurring outside of it, on the surrounding, film-covered surface (2). In the case of the samples in the present study, which were anodically polarized to some extent due to coupling with steel samples, the oxygen cathodic half-cell reaction may not occur at all on the aluminum surface, but rather on the steel cathode in the galvanic couple; this does not affect the argument that follows whatsoever. Typically, a high cathode-to-anode surface area ratio is set up once the pitting situation is created, so that a high local anodic current density is created in the pit sites. Also, because there is limited access of 0, to the pit interior, the 02 concentration in the pit solution (the anolyte) rapidly becomes nil (2). The generally accepted theories for pitting (2) then argue that due to the resultant local buildup of positive charge due to metal ion concentration within the pit, migration of anions from the bulk solution is encouraged to maintain charge balance, and that particularly the mobile Cl ion, if present, will be attracted to the pit interior. Of course in seawater, there is an available supply of Cl ions, and it is considered that when the anolyte composition becomes sufficiently concentrated in Al +++ and Cl -, a hydrolysis (water breakdown) reaction occurs (2). This may be represented by a reaction such as:

(3) 
$$A1^{+++} + C1^{-} + 3H_2O \rightarrow A1 \text{ (OH) 3 (S) } 3H^{+} + 3C1^{-}.$$

Note that this reaction creates a solid corrosion product and lowers the pH within the pit, while maintaining the chloride ion concentration. Since both the low pH and high Cl<sup>-</sup> ion concentration tend to facilitate the anodic dissolution reaction, the overall process tends to accelerate; this is sometimes referred to as autocatalytic behavior (2). In most models of the pitting process, formation of the solid corrosion product is assumed to occur at the mouth of the pit, as a membrane or mound (3), which serves to further isolate the pit solution (anolyte) from the bulk solution; the occluded cell situation is enhanced. In the present study we are able to see directly the enhanced local generation of solid corrosion product at the pit sites. We see both solid mounds (Alloys G and R) and thin membranes (Alloy K) over pit entrances in the alloys discussed in this paper. It is also evident here that the solid corrosion products precipitate in such a way as to effectively seal the pit mouth, to the extent that hydrogen gas generation within the pit can build up pressure and physically move or deform the mound.

It is well known that the anolyte composition changes considerably during pit propagation (2), with a large decrease in pH and simultaneous increase in aggressive anion concentration. It is also well accepted that in this acidic occluded cell, reduction of hydrogen ions will occur, according to the reaction

(4) 
$$2H^{+} + 2e^{-} \rightarrow 2H \rightarrow H_{2}(g)$$

creating hydrogen gas (4). Even in single metal situations, it is known that this reaction of H<sub>2</sub> evolution within pits plays an important role in supporting the anodic dissolution reaction, and under conditions of increased anodic polarization, H<sub>2</sub> gas evolution from within pits is quite evident (3). The classic study of Edeleanu and Evans (2) included direct observation that (hydrogen) gas bubbles come from within pits in the anodic attack of aluminum. With the present microscopic observations we are able to directly confirm the existence of a continuous formation process for the solid corrosion product of equation (3), as well as observe its morphology, and from the morphological observations we are able, by strong inference, to support the concept of hydrogen gas evolution within pits represented by equation (4). The gas is evolved within a sealed cell, and builds up pressure that may be released periodically by extruding the solid corrosion product out of the pit mouth, or which may act continuously to form inflated hemispherical shells over the pit

opening. Further study is required to determine the factors which cause these different morphological manifestations of the basic pitting reactions. Certainly, variations in the base alloy composition and consequent variations in the character of the surface films are likely to have important influences.

#### Acknowledgement

This work was supported by the Office of Naval Research through contract N00014-78-WR-80105, NR-036-120.

#### REFERENCES

- 1. J. Perkins, J. R. Cummings, R. A. Reinhardt, and K. J. Graham, "Corrosion Behavior of Aluminum Alloys Intended for Sacrificial Anode Applications in Seawater," NPS-69PS-78-002, Technical Report No. 6 prepared for the Office of Naval Research, Contract N00014-78-WR-80105, NR-036-120, March 1978.
- 2. C. Edeleanu and U. R. Evans, "The Causes of the Localized Character of Corrosion on Aluminum," Trans. Faraday Soc. 47, 1121 (1951).
- 3. J. A. Richardson and G. C. Wood, "A Study of the Pitting Corrosion of Alby Scanning Electron Microscopy," <u>Corros. Sci.</u> 10, 313-323 (1970).
- 4. G. C. Wood, W. H. Sutton, J. A. Richardson, T. N. K. Riley, and A. G. Malherbe, "The Mechanism of Pitting of Aluminum and Its Alloys," pp. 526-546 in Localized Corrosion, Nat'l Assoc. Corros. Eng., 1974.
- 5. F. D. Bogar and R. T. Foley, "The Influence of Chloride Ion on the Pitting of Aluminum," J. Electrochem Soc. 119, 462 (1972).
- 6. W. K. Johnson, "Recent Developments in Pitting Corrosion of Aluminum," Br. Corros. J. 6, 200 (1971).
- 7. M. J. Pryor, "Electrode Reactions on Oxide Covered Aluminum," Z.Electrochem 62, 782 (1958).
- 8. M. A. Heine, D. S. Keir, and M. J. Pryor, "The Specific Effects of Chloride and Sulfate Ions on Oxide-Covered Aluminum," <u>J. Electrochem. Soc.</u> 112, 24 (1965).
- 9. H. Bohni and H. H. Uhlig, "Environmental Factors Affecting the Critical Pitting Potential of Aluminum," J. Electrochem. Soc. 116, 906 (1969).
- 10. J. R. Gavele, "Transport Processes and the Mechanism of Pitting of Metals," J. Electrochem. Soc. 123, 464 (1976).
- 11. M. J. Pryor, "The Influence of the Defect Structure of Aluminum Oxide Films on the Pitting of Aluminum Chloride Solutions," pp. 2-11, in <u>Localized Corrosion</u>, Nat'l Assoc. Corros. Eng., 1974.

TABLE I: NOMINAL COMPOSITIONS OF ALUMINUM ALLOYS

Alloy	<u>G*</u>	<u>R**</u>	<u>K***</u>
Нд	0.047%	0.03-0.06%	
Zn	0.45%	1.25-2.0%	6.0-7.4%
Cu	0.019%	0.003% max	0.005% max
Fe	0.034%	0.007% max	0.10% max
Sn			0.12-0.20%
Si			0.10% max

\*Alloy G: Galvalum®I (Dow Chemical USA)

\*\*Alloy R: Reynode PII (Reynolds Metal Company)

\*\*\*Alloy K: KA-90® (Kaiser Magnesium Company)

#### LIST OF FIGURES

- Figure 1: Macroscopic dissolution behavior of the aluminum anodic samples in synthetic seawater. Alloy G initiates attack which spreads laterally inward from the specimen edges. Alloy R forms elongated cavities on the broad faces of the specimen. Alloy K forms more (and smaller) dissolution sites per unit surface area.
- Figure 2: Microscopic dissolution morphology found within the dissolution regions of the respective alloys. Alloy G displays a distinct step pattern on all grain surfaces, whereas Alloy R forms surfaces usually made up of sharp peaks; both Alloy G and R accumulate little corrosion product on the dissolution surface. If the corrosion product is removed from Alloy K, a less distinct step structure is seen, with intergranular penetration.
- Figure 3: Microscopic observations of true (occluded cell) pitting phenomena observed within the dissolution regions of Alloys G and K when these regions become somewhat filmed over (after several days exposure). Alloys G and K develop mounds with smooth hemispherical caps that emerge from the pit mouths within a cracked film. Alloy K develops inflated pod-like domes in the general film on the unattacked regions of the anode.
- Figure 4: Less frequently observed are pitting and mound features on the unattacked regions of alloys G and R.
- Figure 5: Broken hemispherical pod on Alloy K; note the interior filament of corrosion product emerging from the pit mouth.




Figure 1: Macroscopic dissolution behavior of the aluminum anodic samples in synthetic seawater. Alloy G initiates attack which spreads laterally inward from the specimen edges. Alloy R forms elongated cavities on the broad faces of the specimen. Alloy K forms more (and smaller) dissolution sites per unit surface area.




Figure 2: Microscopic dissolution morphology found within the dissolution regions of the respective alloys. Alloy G displays a distinct step pattern on all grain surfaces, whereas Alloy R forms surfaces usually made up of sharp peaks; both Alloy G and R accumulate little corrosion product on the dissolution surface. If the corrosion product is removed from Alloy K, a less distinct step structure is seen, with intergranular penetration.




Figure 3: Microscopic observations of true (occluded cell) pitting phenomena observed within the dissolution regions of Alloys G and K when these regions become somewhat filmed over (after several days exposure). Alloys G and K develop mounds with smooth hemispherical caps that emerge from the pit mouths within a cracked film. Alloy K develops inflated pod-like domes in the general film on the unattacked regions of the anode.



Figure 4: Less frequently observed are pitting and mound features on the unattacked regions of alloys G and R.




Figure 5: Broken hemispherical pod on Alloy K; note the interior filament of corrosion product emerging from the pit mouth.

#### INITIAL DISTRIBUTION LIST

		No. Copies
1.	Defense Documentation Center Cameron Station Alexandria, Virginia 22314	2
2.	Library, Code 0142 Naval Postgraduate School Monterey, California 93940	2
3.	Department Chairman, Code 69 Department of Mechanical Engineering Naval Postgraduate School Monterey, California 93940	2
4.	Naval Research Laboratory Washington, D. C. 20390 Code 2627	1
5.	Naval Air Propulsion Test Center Trenton, NJ 08628 Attn: Library	1
6.	Office of Naval Research Department of the Navy (Attn:Code 471) 800 N. Quincy Street Arlington, VA 22217	1
7.	Naval Air Development Center Code 302 Warminster, PA 18974 Attn: Mr. F. S. Williams	1
8.	Naval Construction Battalion Civil Engineering Laboratory Port Hueneme, CA 93043 Attn: Materials Division	1
9.	Office of Naval Research 800 N. Quincy Street Arlington, VA 22217 Attn: Code 102	1
10.	Naval Electronics Lab. Center San Diego, CA 92152 Attn: Electron Materials Sciences Division	1
11.	Naval Missile Center Materials Consultant Code 3312-1 Point Mugu, CA 93041	1

12.	Office of Naval Research 800 N. Quincy Street Arlington, VA 22217 Attn: Code 470	1
13.	Commanding Officer Naval Surface Weapons Center White Oak Laboratory Silver Spring, MD 20910	1
14.	David W. Taylor Naval Ship R & D Center Materials Department Annapolis, MD 21402	1
15.	Commanding Officer Office of Naval Research Branch Office 495 Summer Street Boston, MA 02210	1
16.	Naval Undersea Center San Diego, CA 92132 Attn: Library	1
17.	Naval Underwater System Center Newport, RI 02840 Attn: Library	1
18.	Commanding Officer Office of Naval Research Branch Office 536 S. Clark Street Chicago, IL 60605	1
19.	Naval Weapons Center China Lake, CA 93555 Attn: Library	1
20.	Naval Air Systems Command Washington, D. C. 20360 Attn: Code 52031	1
21.	Office of Naval Research San Francisco Area Office 760 Market Street, Rm 447 San Francisco, CA 94102	1
22.	Naval Air Systems Command Washington, D. C. Attn: Code 52032	1
23.	Naval Air Systems Command Washington, D. C. 20360 Attn: Code 320	1

24	Naval Research Lab. Washington, DC 20390 Attn: Code 6000	1
25	Naval Sea System Command Washington, DC 20362 Attn: Code 035	1
26	. NASA Headquarters Washington, D. C. Attn: Code RRM	1
27	. Naval Research Lab. Washington, DC 20390 Attn: Code 6100	1
28	. Naval Facilities Engineering Command Alexandria, VA 22331 Attn: Code 03	1
29	. NASA Lewis Research Center 20111 Brookpark Road Cleveland, Ohio 44135 Attn: Library	1
30	Naval Research Lab. Washington, D.C. 20390 Attn: Code 6300	1
31.	. Scientific Advisor Commandant of the Marine Corps Washington, D. C. 20380 Code AX	1
32.	. National Bureau of Standards Washington, DC 20234 Attn: Metallurgy Division Inorganic Mat. Div.	1
33.	Dr. Wm. R. Prindle National Academy of Sciences National Research Council 2101 Constitution Ave. Washington, DC20418	1
34.	. Dr. R. P. Wei, Lehigh Univ. Inst. for Fracture & Solid Mechanics Bethlehem, PA 18015	1
35.	Prof. H. G. F. Wilsdorf Univ. of Virginia Dept. of Mat. Science Charlottesville VA 22903	1

36.	Defense Metals and Ceramics Info Center Battelle Mem. Institute 505 King Ave. Columbus, Ohio 43201	1
37.	Naval Ship Engr. Center CTR BG #2 Code 6101 3700 E-W Highway Prince George Plaza Hyattsville, MD 20782	1
38.	Director, Ordnance Research Lab. P.O. Box 30 State College, PA 16801	1
39.	Army Research Office Box CM, Duke Station Durham, NC 27706 Attn: Metallurgy & Cer. Div.	1
40.	Army Materials and Mechanics Research Center Watertown, MA 02172 Attn: (AMXMR-P)	1
41.	Dir. Applied Physics Lab. University of Washington 1013 NE 40th Street Seattle, WA 98105	1
42.	Metals and Ceramics Div. Oak Ridge Nat'l Lab. P.O. Box X Oak Ridge, TN 37380	1
	AF/Ofc. of Scientific Research Bldg. 410 Bolling AF Base Washington, D. C. 20332 Attn: Chem. Sci. Directorate Electronics & S. S. Sci. Director	1
44.	Los Alamos Scientific Lab P.O. Box 1663 Los Alamos, NM 87544 Attn: Report Librarian	1
45.	AF Materials Lab. (LA) Wright-Patterson AFBase Dayton, Ohio 45433	1
46.	Argonne National Lab. Metallurgy Division P.O. Box 229 Lemont II 60439	1

47.	Dr. J. A. S. Green Martin Marietta Corp. 1450 S. Rolling Road Baltimore, MD 21227	1
48.	Dr. T. R. Beck Electrochemical Tech. Corp. 10035 31st Ave. NE Seattle, WA 98125	•
49.	Prof. R. H. Heidersbach University of Rhode Island Department of Ocean Engr. Kingston, RI 02881	1
50.	Professor I. M. Bernstein Carnegie-Mellon Univ. Schenley Park Pittsburgh, PA 15213	;
51.	Professor H. K. Birnbaum Univ. of Illinois Dept. of Metallurgy Urbana, IL 61801	1
52.	Prof. J. P. Hirth Ohio State University Metallurgical Engineering Columbus, OH 43210	1
53.	Prof. H. Herman State Univ. of New York Materials Science Div. Stony Brook, NY 11794	1
	Dr. Otto Buck Rockwell International 1049 Camino Dos Rios P.O. Box 1085 Thousand Oaks, CA 91360	1
55.	Dr. D. W. Hoeppner University of Missouri College of Engineering Columbia, MO 65201	1
56.	Prof. H. W. Pickering Pennsylvania State Univ. Dept. of Mat. Sciences University Park, PA 16802	1
57.	Dr. David L. Davidson Southwest Research Inst. 8500 Culebra Road P.O. Drawer 28510 San Antonio, TX 78284	1

58.	Dr. E. W. Johnson Westinghouse Electric Corp. Research and Development Center 1310 Beulah Road Pittsburgh, PA 15235	1
59.	Dr. F. Mansfeld Rockwell 1049 Camino Dos Rios P.O. Box 1085 Thousand Oaks, CA 91360	1
60.	Dr. D. J. Duquette Dept. of Metallurgical Engr. Rensselaer Polytechnic Inst. Troy, NY 12181	1
61.	Prof. R. T. Foley The American University Dept. of Chemistry Washington, DC 20016	1
62.	Prof. A. E. Miller University of Notre Dame College of Engineering Notre Dame, IN 46556	1
63.	Mr. G. A. Gehring Ocean City Research Corp. Tennessee Ave. & Beach Thorofare Ocean City, NJ 08226	1
64.	Prof. R. W. Staehle Ohio State University Dept. of Metallurgical Engr. Columbus, OH 43210	1
65.	Dr. Barry C. Syrett Stanford Research Institute 333 Ravenswood Avenue Menlo Park, CA 94025	1
66.	Brookhaven Nat'l Laboratory Technical Info. Div. Upton, LI New York 11973 Attn: Research Library	1
67.	Library Building 50 Rm 134 Lawrence Radiation Laboratory Berkeley, CA 94550	1
68.	Prof. Jeff Perkins Naval Postgraduate School Code (69Ps) Monterey, CA 93940	30

U183501



